



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Supervisor

[Handwritten signature]

Inspection Report
Minerals Regulatory Program
Report Date: June 6, 2005

Mine Name: Dove Creek Mill
Operator or Permittee Name:
Bonneville Quarries, Inc.

Permit number: M/003/047
Inspection Date: May 23 & 24, 2005

Inspector(s): Lynn Kunzler

Weather: clear
Inspection Start Time: 11:30 am
Inspection End Time: 12:30 pm
Site location/Area Inspected (i.e. Pit #):

Other Participants: Mike Nelson and Larry Garahana, BLM
Permit Status: Inactive
Current Acreages: 3.5
Total Permitted (Bonded): 5
Total Disturbed: 3.5

Surface Ownership: BLM
Mineral Ownership: NA
Mineral Mined: Millsite
Type of Mine: Surface

Elements of Inspection	Evaluated	N/A	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (open shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Explosives, magazines	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Concurrent Reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Demolition	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Backfilling and Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Other	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:


Check status while in the area.

Inspection Summary:

1. This site has been inactive for about 5 years. The BLM has requested that this site be reclaimed. I met with Mr. Bill Bown at another site - he indicated that he was starting reclamation of this site. I stopped by while in the area to see how reclamation was proceeding.
7. Reclamation has started, work is being done by Lynn Palmer. He is loading waste rock into dump trucks and hauling to rancher in the area that would like to use it for road base. Will take a couple weeks to complete. Once the rock is removed, the area will be ripped and seeded.
15. While at the site, a tanker truck, a heavy hauler, a 5th wheel camp trailer, 100+ horse 4WD tractor with brush beater, trackhoe and front end loader were observed on site (this equipment does not belong to Palmer or Bown). They knew nothing about them. I called the BLM - they are not aware of anyone else with a permit to be there. Name on trucks was: Allen Water Tender Service, Inc.(Idaho registration) BLM will send someone to investigate tomorrow (5/24) When BLM arrived at the site, they indicated that the Fire Crew had contracted with someone to do fuel management on this section. They were not sure of the contractor, but the equipment on site would be consistent with the program.

No other problems noted.

Inspector's Signature _____



Date: June 6, 2005

LK:jb